

[\(close window\)](#)

Motosport Hillsboro - Honda Suzuki Kawasaki

KTM

809 NE 28th Avenue

Hillsboro, OR 97124

(503) 648-4555

www.hillsboromotorcycles.com

**2005 SUZUKI
VL1500, C90,T 2005-
2006**

OIL PUMP

July 12, 2007





FIG.15

VL1500K5 E03 E28_015
OIL PUMP

REF#	PART	#REQ	REMARKS	YOUR PRICE
1	PUMP ASSY, OIL 16400-38B10	1		\$109.37
2	BOLT 01547-06453	1		\$1.11
3	BOLT, OUTER COVER	1		\$1.11

4	01547-06553 .BOLT 01547-06653	1	\$1.37
5	GEAR, OIL PUMP DRIVEN (NT:31) 16331-38B01	1	\$36.95
6	WASHER (12X20X0.5) 09181-12158	1	\$1.15
7	PIN 09261-05006	1	\$0.74
8	CIRCLIP 08331-31126	1	\$0.89
9	VALVE ASSY, OIL RELIEF 16440-17C20	1	\$27.28
10	GASKET (16X22X2.0) 09168-16002	1	\$0.93
11	FILTER, ENGINE OIL 16510-03G00-X07	1	\$9.80
12	STRAINER, OIL 16520-38B10	1	\$13.68
13	BOLT 01550-05103	4	\$0.96
14	HOLDER, OIL STRAINER 16525-38B10	1	\$18.44
15	BOLT 01550-0625A	2	\$1.04
16	O RING (D:3.1,ID:22.7) 09280-22008	1	\$1.04

[\(close window\)](#)

**Motosport Hillsboro - Honda Suzuki Kawasaki
KTM**
809 NE 28th Avenue
Hillsboro, OR 97124
(503) 648-4555
www.hillsboromotorcycles.com

**2005 SUZUKI
VL1500, C90,T 2005-
2006**

July 12, 2007

(prices subject to change without notice)

