

[\(close window\)](#)

Motosport Hillsboro - Honda Suzuki Kawasaki

KTM

809 NE 28th Avenue

Hillsboro, OR 97124

(503) 648-4555

www.hillsboromotorcycles.com

2005 SUZUKI
VL1500, C90,T 2005-
2006
2ND AIR
July 12, 2007





FIG.18

VL1500K5 E03 E28_018
2ND AIR

REF#	PART	#REQ	REMARKS	YOUR PRICE
1	COVER, 2ND AIR 13741-41F11	1		\$139.96
2	PIPE, 2ND AIR FR 18410-10F20	1		\$25.24
3	PIPE, 2ND AIR RR	1		\$30.71

4	18420-10F20 GASKET, 2ND AIR PIPE 18441-45C01	2	\$3.85
5	VALVE ASSY, 2ND AIR 18450-10F40	1	\$119.77
6	HOSE, 2ND AIR VALVE 18461-10F20	2	\$11.83
7	BRACKET, 2ND AIR S 18610-10F20	1	\$47.50
8	HOSE, 2ND AIR CLNR 18711-10F20	1	\$8.43
9	CUSHION, 2ND AIR COV 18788-10F20	1	\$7.84
10	CLIP, FUEL HOSE 09401-13414	4	\$1.26
11	CLIP 09401-15101	2	\$1.15
12	BOLT, 2ND AIR VALVE CUSHION 17788-13612	2	\$5.73
13	BOLT, STUD 01421-06163	4	\$0.93
14	NUT 08316-1006A	4	\$1.11
15	SPACER, 2ND AIR SP 18630-10F20	3	\$4.88
16	BOLT 09116-06176	3	\$1.67
17	CUSHION 09320-10014	3	\$1.41
18	.CUSHION 13747-41F00	2	\$1.63
19	.WASHER 13833-41F00	2	\$1.63
20	SCREW, BRACE 09139-06126	2	\$2.18
21	NUT 08316-1006A	2	\$1.11

[\(close window\)](#)

Motosport Hillsboro - Honda Suzuki Kawasaki

KTM

809 NE 28th Avenue

Hillsboro, OR 97124


(503) 648-4555

www.hillsboromotorcycles.com

**2005 SUZUKI
VL1500, C90,T 2005-
2006**

July 12, 2007

(prices subject to change without notice)



print