

[\(close window\)](#)

Motosport Hillsboro - Honda Suzuki Kawasaki

KTM

809 NE 28th Avenue

Hillsboro, OR 97124

(503) 648-4555

www.hillsboromotorcycles.com

**2005 SUZUKI
VL1500, C90,T 2005-
2006
ELECTRICAL**

July 12, 2007





FIG.27

VL1500K5 E03 E28_027
ELECTRICAL

REF#	PART	#REQ	REMARKS	YOUR PRICE
1	RELAY ASSY, STARTING MOTOR 31800-21E20	1		\$54.72
2	.COVER 31861C47E00J000	1		\$1.52
3	.FUSE (30A)	2		\$1.15

	09481-30101		
4	BOLT, STARTING MOTOR (6X8) 09128-06013	2	\$0.67
5	WIRE, STARTER MOTOR LEAD 33810-10F00	1	\$17.74
6	.CAP, STARTER MOTOR 31861-48B10	1	\$2.92
7	RECTIFIER ASSY 32800-41F10	1	\$170.61
8	BOLT 02162-0625A	2	\$0.85
9-1	CONTROL UNIT, FI 32920-10F10	1	\$741.98
9-2	CONTROL UNIT, FI 32920-10F30	1	\$741.98
10	SENSOR ASSY, FUEL CUT 33960-06G10	1	\$48.34
11	BRACKET, FUEL CUT 33961-10F00	1	\$4.03
12	SPACER, IGN COIL BRKT 09180-06325	1	\$2.00
13	CUSHION 09320C08051J000	1	\$1.74
14	BOLT 01550-0616A	1	\$1.04
15	COIL ASSY, IGNITION REAR 33410-10F10	1	\$73.40
16	SPACER, IGN COIL REAR 09180-06195	2	\$1.89
17	BOLT 01547-05403	2	\$1.08
18	COIL ASSY, IGNITION FRONT 33420-10F10	1	\$71.32
19	SPACER, IGN COIL REAR 09180-06195	2	\$1.89
20	BOLT 01547-05403	2	\$1.08
21	CAP, SPARK PLUG 33510-38B00	2	\$14.19
22	SEAL, SPARK PLUG CAP (SIDE) 33541-47D00	2	\$4.22
23	SEAL, HIGH TENSION CORD 33542-38B00	2	\$2.29
24	RELAY ASSY, DEF LOCK 38740-31G10	1	\$19.55
25	SOLENOID ASSY, DECOMP 33970-10F00	1	\$168.25
26	STOPPER, DECOMP SOLENOID 33971-10F00	1	\$2.78
27	PLUG, T/M OIL DRAIN 01550-0816A	2	\$1.19
28	CUSHION, DECOMP (8X27X3) 33652-19B00	1	\$3.14
29	CUSHION, DECOMP 33972-31D10	1	\$2.15
30	CABLE, DECOMP FRONT 58900-10F00	1	\$9.35
31	CLAMP (L:235) 09407-25401	1	\$2.44

[\(close window\)](#)

Motosport Hillsboro - Honda Suzuki Kawasaki KTM


809 NE 28th Avenue
Hillsboro, OR 97124
(503) 648-4555

www.hillsboromotorcycles.com

**2005 SUZUKI
VL1500, C90,T 2005-
2006**

July 12, 2007

(prices subject to change without notice)



print