

[\(close window\)](#)

**Motosport Hillsboro - Honda Suzuki Kawasaki**

**KTM**

**809 NE 28th Avenue**


**Hillsboro, OR 97124**


**(503) 648-4555**

[www.hillsboromotorcycles.com](http://www.hillsboromotorcycles.com)

**2005 SUZUKI**  
**VL1500, C90,T 2005-**  
**2006**  
**CAM CHAIN**

July 12, 2007



**FIG.11**

VL1500K5 E03 E28\_011  
CAM CHAIN

REF#	PART	#REQ	REMARKS	YOUR PRICE
1	CHAIN, CAM SHAFT DRIVE 12760-38B00	2		\$62.66
2	GUIDE, CAM CHAIN 12771-38B00	1		\$30.94
3	GUIDE, CAM CHAIN REAR	1		\$30.94

	12771-10F00		
4	TENSIONER, CAM CHAIN 12811-38B00	2	\$30.31
5	BOLT (6X26) 09100-06129	2	\$0.93
6	WASHER 08211-06182	4	\$0.76
8	ADJUSTER ASSY, TENSIONER FRON 12831-38A01	1	\$67.85
9	BOLT 07130-06203	2	\$1.26
10	BOLT (6X45) 07130-06453	2	\$1.59
11	ADJUSTER ASSY, TENSIONER REAR 12832-38A01	1	\$67.85

[\(close window\)](#)**Motosport Hillsboro - Honda Suzuki Kawasaki****KTM****809 NE 28th Avenue****Hillsboro, OR 97124****(503) 648-4555**[www.hillsboromotorcycles.com](http://www.hillsboromotorcycles.com)**2005 SUZUKI  
VL1500, C90,T 2005-  
2006**

July 12, 2007

(prices subject to change without notice)

