

[\(close window\)](#)

Motosport Hillsboro - Honda Suzuki Kawasaki

KTM

809 NE 28th Avenue

Hillsboro, OR 97124

(503) 648-4555

www.hillsboromotorcycles.com

**2005 SUZUKI
VL1500, C90,T 2005-
2006
OIL COOLER**

July 12, 2007





FIG.16

VL1500K5 E03 E28_016
OIL COOLER

REF#	PART	#REQ	REMARKS	YOUR PRICE
1	COOLER ASSY, OIL 16600-10F00	1		\$347.61
2	BOLT 09116-06167	3		\$1.11
3	.SPACER	2		\$0.93

4	09180-06310 SPACER 09180-07004	1	\$1.08
5	CUSHION 09320-10015	3	\$1.19
6	COVER, OIL COOLER 16621-10F00	1	\$63.06
7	BOLT (6X12) 09139-06091	4	\$1.59
8	HOSE, OIL COOLER RH 16460-10F10	1	\$84.92
9	HOSE, OIL COOLER LH 16470-10F10	1	\$84.92
10	BOLT 09360-14012-A05	2	\$5.55
11	BOLT, DELIVERY PIPE UNION 09360-14009	2	\$6.06
12	GASKET, OIL PIPE UNION BOLT 09168-14015	8	\$1.08

[\(close window\)](#)

**Motosport Hillsboro - Honda Suzuki Kawasaki
KTM**

**809 NE 28th Avenue
Hillsboro, OR 97124
(503) 648-4555**

www.hillsboromotorcycles.com

**2005 SUZUKI
VL1500, C90,T 2005-
2006**

July 12, 2007

(prices subject to change without notice)

