

[\(close window\)](#)


**Motosport Hillsboro - Honda Suzuki Kawasaki  
KTM**


**809 NE 28th Avenue  
Hillsboro, OR 97124  
(503) 648-4555**

[www.hillsboromotorcycles.com](http://www.hillsboromotorcycles.com)

**2005 SUZUKI  
VL1500, C90,T 2005-  
2006  
CYLINDER HEAD  
(REAR)**

July 12, 2007



**FIG.3**

VL1500K5 E03 E28\_003  
CYLINDER HEAD (REAR)

REF#	PART	#REQ	REMARKS	YOUR PRICE
1	HEAD ASSY, CYLINDER REAR 11103-10F10	1		\$725.27
2	.SNAP RING 09381-10004	2		\$0.67
3	.RING, VALVE GUIDE	1		\$0.74

	09381-10003		
4	PIN 09206-08001	2	\$0.89
5	BOLT (6X60) 09103-06064	2	\$1.08
6	BOLT (6X55) 09103-06102	2	\$1.08
7	GUIDE, VALVE INTAKE (OS:0.3) 11115-38B70	2	\$9.94
8	GUIDE, VALVE (OS:0.3) 11115-45740	1	\$9.94
9	GASKET, CYLINDER HEAD REAR 11142-10F00	1	\$27.46
10	PIN 04211-13189	2	\$1.11
11	BOLT, SENSOR GUIDE 07120-06123	1	\$1.22
12	GASKET, TENSIONER ADJUSTER 09168-06018	1	\$0.82
13	STUD BOLT (8X30) 09108-08142	1	\$1.63
14	STUD BOLT (M12/8) 09108-08205	1	\$6.06
15	NUT, IDLE GEAR SHAFT 08316-1008A	2	\$1.15
16	WASHER (10.5X22X2.3) 09160-10039	3	\$1.15
17	GASKET 09168-10017	1	\$1.59
18	BOLT 09103-08181	1	\$1.96
19	BOLT (10X180) 09103-10178	1	\$7.76
20	BOLT (10X190) 09103-10179	1	\$7.76
21	BOLT (10X200) 09103-10180	1	\$7.76
22	BOLT (10X215) 09103-10181	1	\$8.21
23	BOLT (6X50) 09103-06101	4	\$1.08
24	BOLT (6X45) 09103-06112	2	\$1.08
26	BOLT (8X268) 09103-08213	2	\$11.53
27	BOLT 01550-0630A	4	\$1.19
28	BOLT 01550-0635A	1	\$1.19
29	WASHER (8.5X24X1.6) 09160-08130	2	\$1.08
30	WASHER, OIL GALLERY EXHAUST 09168-06023	6	\$1.08
31-1	SPARK PLUG, DPR7EA-9 (NGK) 09482-00354	1	\$2.32
31-2	SPARK PLUG, DPR7EA-9 (NGK) 09482-00354	1	\$2.32
31-3	SPARK PLUG (NGK, DPR8EA-9) 09482-00334	1	\$2.32
31-4	SPARK PLUG (ND, X24EPR-U9) 09482-00335	1	\$3.60
31-5	SPARK PLUG, DPR9EA-9 (NGK) 09482-00330	1	\$2.10
31-6	SPARK PLUG, X27EPR-U9 (ND) 09482-00331	1	\$3.60
32	CAP, HEAD COVER LH 11173-10F00	1	\$82.63
33	CAP, HEAD COVER RH 11174-10F00	1	\$82.63
34	CUSHION, HEAD COVER CAP 11273-24B00	2	\$2.29
35	WASHER (6.5X18X1.6) 09160-06084	2	\$0.89
36	WASHER, HEAD COVER CAP LOWER 09160-09016	2	\$0.93
37	CUSHION, HOLDER 09320-09016	2	\$1.08
38	BOLT, HEAD COVER CAP NO.1 01547-06707	1	\$1.37
39	BOLT 01547-06507	1	\$1.19
40	SPACER, HEAD COVER CAP NO.1	1	\$7.25

	11179-10F00		
41	SPACER, HEAD COVER CAP 11179-10F10	1	\$5.40
42	CUSHION, HEAD COVER BOLT 09320-13015	2	\$1.37
43	PLUG, CYLINDER HEAD 09241-30008	1	\$3.70
44	BUSH, HEAD COVER BOLT 09301-08007	2	\$2.81
45	PLUG, WATER GALLERY (22X11) 09248-22004	1	\$6.80
46	PIPE, INTAKE REAR 13102-10F10	1	\$45.55
47	.O RING (D:1.9,ID:40.7) 09280-41007	1	\$4.55
48	BOLT 09119-06092	2	\$1.11
49	CLAMP 09402-62203	1	\$3.44

[\(close window\)](#)

**Motosport Hillsboro - Honda Suzuki Kawasaki  
KTM**  
809 NE 28th Avenue  
Hillsboro, OR 97124  
(503) 648-4555  
[www.hillsboromotorcycles.com](http://www.hillsboromotorcycles.com)

**2005 SUZUKI  
VL1500, C90,T 2005-  
2006**  
July 12, 2007  
(prices subject to change without notice)

