

[\(close window\)](#)

Motosport Hillsboro - Honda Suzuki Kawasaki

KTM

809 NE 28th Avenue

Hillsboro, OR 97124


(503) 648-4555

www.hillsboromotorcycles.com

**2005 SUZUKI
VL1500, C90,T 2005-
2006**

REAR WHEEL

July 12, 2007



This exploded view diagram illustrates the assembly of a vehicle wheel and suspension system. The components are numbered as follows:

- Wheel Assembly (Top):**
 - 1: Wheel rim
 - 2: Wheel hub
 - 3: Wheel axle
 - 4: Wheel nut
 - 5: Wheel washer
 - 6: Wheel flange
 - 7: Wheel bolt
 - 12: Wheel nut
 - 14: Wheel washer
 - 15: Wheel washer
 - 16: Wheel nut
 - 22: Wheel flange
 - 23: Wheel nut
 - 24: Wheel washer
- Suspension Assembly (Bottom):**
 - 2: Wheel hub
 - 8: Suspension arm
 - 9: Suspension arm nut
 - 10: Suspension arm washer
 - 11: Suspension arm
 - 12: Suspension arm nut
 - 13: Suspension arm washer
 - 14: Suspension arm washer
 - 15: Suspension arm washer
 - 16: Suspension arm nut
 - 17: Suspension arm
 - 18: Suspension arm washer
 - 19: Suspension arm washer
 - 20: Suspension arm washer
 - 21: Suspension arm washer

A 'FWD' arrow points to the left, indicating the front of the vehicle.

VL1500K5 E03 E28_056
REAR WHEEL

REF#	PART	#REQ	REMARKS	YOUR PRICE
1	WHEEL SET, REAR (MT5.00X15) 64100-10830-YAA	1		\$755.38
2	.BUSH, REAR HUB 09319-12019	6		\$6.62
3	SPACER, REAR HUB BEARING	1		\$15.56

	09180-20112		
4	BEARING, RH 08133-62047	1	\$14.74
5	BEARING, REAR HUB, LH 09262-20042	2	\$12.49
6	DISC, REAR BRAKE 69210-10F22	1	\$310.24
7	BOLT (8X33) 09106-08148	6	\$2.59
8	BRACKET, REAR CALIPER 69721-10F01	1	\$76.01
9	PIN, BRACKET 64241-10F00	1	\$12.01
10	NUT 08319-31123	1	\$2.00
11	AXLE, REAR 64711-10F00	1	\$61.10
12	SPACER, AXLE RH 64740-10F00	1	\$11.98
13	SPACER, AXLE LH 64772-10F00	1	\$11.09
14	WASHER 08322-01183	1	\$0.93
15	NUT 09159-18004	1	\$10.65
16	CAP, LH 64792-38B00	2	\$10.43
17	JOINT, HUB DRIVEN 64680-24A00	1	\$117.12
18	O RING, DRIVEN JOINT 09280-65003	1	\$1.59
19	WASHER, THRUST 64677-45110	3	\$1.41
20	BOLT, DRIVEN JOINT WASHER 09119-06049	6	\$0.74
21	WASHER, JOINT 09169-06030	3	\$1.26
22-1	TIRE, REAR (180/70-15M/C 76H) 65110-10F00	1	\$272.93
22-2	TIRE, REAR (180/70-15M/C 76H) 65110-10F10	1	\$289.53
23	VALVE ASSY, WHEEL RIM (TR412) 43130-24A00	1	\$4.81
24-1	BALANCER, WHEEL (10G) 43222-73H10	0~3	\$2.52
24-2	BALANCER, WHEEL (20G) 43224-73H10	0~3	\$2.78
24-3	BALANCER, WHEEL (30G) 43226-73H10	0~3	\$3.18

[\(close window\)](#)

Motosport Hillsboro - Honda Suzuki Kawasaki KTM


809 NE 28th Avenue
Hillsboro, OR 97124
(503) 648-4555

www.hillsboromotorcycles.com

**2005 SUZUKI
VL1500, C90,T 2005-
2006**

July 12, 2007

(prices subject to change without notice)



print